

	Type	Hits	Search Text
1	IS&R	2476	(174/35r).CCLS.
2	BRS	8	"943203"
3	BRS	1	((174/35r).CCLS.) and (laminate and enclosure and sensor)
4	BRS	4	((174/35r).CCLS.) and (laminate and sensor)
5	BRS	99	((174/35r).CCLS.) and (laminate)
6	BRS	680	(laminate and enclosure and sensor)
7	BRS	6	(laminate same enclosure same sensor)
8	BRS	842	sensor and (cover lid cap) near5 laminat\$3
9	BRS	362	sensor and (enclosure housing package) and (cover lid cap) near5 laminat\$3
10	IS&R	2961	(73/514.16-514.39).CCLS.
11	BRS	122	((73/514.16-514.39).CCLS.) and laminat\$3

	DBs	Time Stamp	Comments	Error Definition
1	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 14:54		
2	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 14:54		
3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 15:50		
4	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 15:00		
5	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 15:00		
6	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 16:01		
7	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 15:52		
8	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 16:07		
9	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 17:23		
10	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/16 17:32		
11	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/09/17 10:21		